	rjngroup	-	imore - Bureau of Water and W onitoring Services for Sanitary Sewer Sy				er	Site Name PA04	
	Excellence through Ownership Sewershed	Project No.				City MH I.D.			
	Sewersned	Project No.	_	Inspection Date/Time 12/14/05 15:30			S47G2_0		
	PATAPSCO	995R	Inspected By			Mar	hole	Pipe	
	TATAL SCO	995K		JM/JS		Depth (ft)	Width (ft)	Width (in)	Height (in)
	Site Address:	4512 (3171735		19.30	4.00	18.00	18.00	
	MH Type: Brick Pre-cast	Pipe Type: O Brick	Pipe Type: O Brick O Concrete O Clay Oth			Pipe Shape:	Circular	○ Box	Odd
A - SITE INVESTIGATION	15			rea Location Map			Safety Concerns		
	30th Ave			netery 173			O D/S In the Manhole Coordinates		
.SI		Cemetery 695 Baltimore Beltway Inner					1,429,408.49 W		
PART A	Area View Picture			Vicinity Map			Asphalt Concrete Signal Strengt	Telog Phone	75%
							(410) 215-4829		
							System Characteristics Residential		
	The state of the s							Commercial	
								ıl	
	Hydraulic Assessment								
	Surcharge (ft): 0.00								s Cleaning
	Flow Depth (in): 5.00	Instant Vel (fps)	0.82	Sil	lt Level (in):	2.50	Signs of I/I:	NO	
	1, ()						Recomme		● Yes
	HYDRAULIC RATING:	O A (good)	B (questi	onable)	O C (poo	r)	Install		O No
							Meter Ty	pe: ADS-F	lowShark
	Installation Plan Sketch Installation						Profile Sketch	1	
PART B - SITE INSTALLATION	19.30' 15.25' 18""			P				2.5" Silt	
INS	Installation Information				0.5		Installation	on Photo	
ITE	Υ : μ 1	Incoming 2 3	oming Outgoing OF 3 4 1 1					712	
3 - S	Line # 1 Size (in) 8.00	<i>m</i>	4	20.63	1			1.	
RT.	Material VCP	e		VCP				11	
PA	Debris (Y/N) Y	t		Y		11		.1	100
	Shape Cir.	e		Cir.				75	
	Flow Depth (in): 0.50	r		5.00					NA
	Instant. Vel. (fps) N/A			0.81		Mr. Alexander			4-1
	Comments: Heavy traffic with parked cars in area, so access might be a problem.								